




Pierce Chair




Parts List




Base



Seat Pan




T-Bushing
5 places



M4 x 14 Thread
Forming Screw
5 places

Pierce Chair



Use bumpers and caution when installing the seat, do not apply excessive pressure and push screw through seat pan